

## TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION **DIVISION OF SOLID WASTE MANAGEMENT** SOLID WASTE DISPOSAL FACILITY EVALUATION

| NAME OF SITE                             |  | REGISTRATION NUMBER   | DATE                                  |
|--|--|---|---------------------------------------|
| Pickett County Class                     | T Landfill   | SNL 69-0244   | 07-30-13                              |
| LOCATION (physical)                      | 1  | PURPOSE (Complete () Follows  | ow-up                                 |
| 516 Moles Road                           |  | () Complaint () Oth   |                                       |
| OWNER/OPERATOR                           |  | TYPE OF FACILITY (CLASS 1   | ( ) CLASS II                          |
| Pickett County                           |  | ( ) CLASS III   | () CLASS IV<br>V1 V2                  |
|  | V1 V2  |   | VI VZ                                 |
| Inadequate vector control                | 8010   | Leachate improperly managed 8330  |                                       |
| Access not limited to operating hours    | 8020   | Inadequate leachate collection  |                                       |
| Inadequate artificial or natural barrier | 8030   | system 8340   | 1                                     |
| Inadequate information signs             | 8040   | Leachate observed at the site 8350                                      |                                       |
| Unsatisfactory access road(s)/parking    |  | Leachate entering runoff 8360   | · · · · · · · · · · · · · · · · · · · |
| area(s)                                  | 8050   | Leachate entering a water   |                                       |
| Certified personnel not present          |  | course 8370   |                                       |
| during operating hours                   | 8060   | Inadequate gas migration control  |                                       |
| Unapproved salvaging of waste            | 8070   | system 8380   |                                       |
| Evidence of open burning                 | 8080   | Inadequate maintenance of gas   |                                       |
| Inadequate fire protection               | 8090   | migration control system 8390   |                                       |
| Unsatisfactory litter control            | 8110   | Potential for explosions or   |                                       |
| Inadequate employee facilities           | 8120   | uncontrolled fires 8420   |                                       |
| No communication devices                 | 8130   | Waste not confined to a   |                                       |
| Inadequate operating equipment           | 8140   | manageable area 8430  |                                       |
| Unavailability of backup equipment       | 8150   | Improper spreading of waste 8440  |                                       |
| Unavailability of cover material         | 8160   | Improper compacting of waste 8450 Unsatisfactory initial cover 8460     |                                       |
| Inadequate maintenance of                |  | Ciloudiciación y minus  |                                       |
| runon/runoff system(s)                   | 8170   | Unsatisfactory intermediate   |                                       |
| Inadequate erosion control               | 8180   | 00101   |                                       |
| Inadequate dust control                  | 8190   | Oliodiolación y milar con es  |                                       |
| Unauthorized waste accepted              | 8210   | LACCOSTVO POOMING OF THE CO.  |                                       |
| Unapproved special waste accepted        | 8220   | Unsatisfactory stabilization of 8510                                    |                                       |
| Tires improperly handled                 | 8230   |   |                                       |
| Medical waste improperly handled         | 8240   | Dumping of waste into water 8520 Unsatisfactory records or reports 8530 |                                       |
| Dead animals improperly handled          | 8250   | Groundwater monitoring system   |                                       |
| Washout of solid waste                   | 8270   | improperly maintained 8540  |                                       |
| No permanent benchmark                   | 8280   | Operation does not correspond   |                                       |
| Inadequate random inspection             | 0000   | with engineering plans 8570   |                                       |
| program                                  | 8290   | Operation does not correspond   |                                       |
| Mishandling of special waste             | 8300   | with permit condition(s) 8580   |                                       |
| Buffer zone standard violated            | 8310   | Permit, plans, operating manual   |                                       |
| Inadequate maintenance of leachate       | 0220   | not available 8590  |                                       |
| management system                        | 8320   | No operating scales 8610  |                                       |
| =  |  | 140 operating source  |                                       |
| COMMENTS:                                |  |   | E                                     |
|  | 11 1 1000 11   | tol   |                                       |
| /VO V/                                   | blations No  | 121   |                                       |
|  |  |   |                                       |
|  |  |   |                                       |
|  |  |   |                                       |
|  |  |   |                                       |
|  |  |   |                                       |
|  |  |   |                                       |
| PERSON INTERVIEWED                       | ull !  | (Signature) Ken Shophen   | £                                     |
| (Signature)                              | Will service the s | TITLE FACE 3  | /                                     |
| TITLE                                    | /  | E133  |                                       |
| TIME OF DAY 10:50 an WEATHER             | CONDITIONS PCC   | 80° COMPLIANCE DATE   | <del>-</del>                          |

Distribution: Facility - White Field Office - Canary

Central Office - XC